IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patentee:

Li Mo, et al.

U.S. Patent No.:

7,075,927 B2

Issue Date:

July 11, 2006

Serial No .:

09/848,994

Filing Date:

May 4, 2001

Confirmation No.:

8984

Title:

Method and System for Quality of Service (QoS) Support in a

Packet-Switched Network

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Dear Sir:

REQUEST FOR CERTIFICATE OF CORRECTION UNDER 37 CFR § 1.322

It is respectfully requested that a Certificate of Correction be issued in accordance with the enclosed Form PTO-1050. The error involved is believed to be a Patent Office error, and it is believed that no fee is due in association with this request for a Certificate of Correction. However, the Commissioner is hereby authorized to charge any fees or credit any overpayments to Deposit Account No. 02-0384 of Baker Botts L.L.P.

It is respectfully submitted that a significant error is present in the printed patent, that correction thereof in accordance with the enclosed Form PTO-1050 is required in order that no misunderstanding will occur.

Respectfully submitted, BAKER BOTTS L.L.P. Attorneys for Applicants

Reg. No. 44,98

Date: 9/8/08

Customer No.: 05073 Phone: (214) 953-6986

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Patent No.: 7,075,927 B2 Dated: July 11, 2006 Inventor(s): Li Mo, et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 9, Line 19, after "GS class" delete "140" and insert -- 148 --. Column 11, Line 15, after "local buffer" delete "152" and insert -- 154 --. Column 14, Line 22, after "and to" delete "combined" and insert -- combine --.

Mailing Address of Sender:

Baker Botts L.L.P. 2001 Ross Avenue, Suite 600 Dallas, Texas 75201-2980 **Patent No.** 7,075,927 B2